Quick Specs Single Phase Input Voltage: 208 - 245 Volts

3 Phase Rated Output: 208 - 245 Volts

Minimum Single Phase Circuit: 170 Amps

Best Performance Single Motor Start: 40HP

Recommended 3 Phase Sizing: 100 Amps

Voltage Balance: +/-2-5% (Based on input)

Professional. Rugged. Affordable. Pro-Line offers more than a traditional phase converter. Built complete and loaded with features.

Control Panel Features


- Integrated Motor Starter with Start/Stop Push Button Switch
- Digitally Controlled & Protected Start Circuit
- Complete Phase Power Failure Protection
- CNC Voltage Balancing
- Power "ON" Indicator Light
- Easy Power Distribution Block Connections
- 10 Year Parts / Lifetime Labor Warranty
- Made In the USA

Idler Generator Features

- Custom Design Rotary Phase Converter Generators
- Low Impedance/High Efficiency Design
- Custom Copper Windings and Rotor
- Made by ABB / Baldor Electric USA
- Available for Indoor and Outdoor
- Soft Start Idler Generator
- Shielded Windings
- Made In the USA











Specifications

Model	
Brand	NAPCES
Line	Pro-Line
Model #	PL-80
General Specifications	
Horse Power (HP)	80
Kilo-watt (kW)	60kW
Frequency (Hz)	60
Generator Type	ODP
Enclosure Type	NEMA 1 (Indoor)
Generator Frame	Twin 324
Single Phase Electrical Specifications	
Voltage Input	208-245
Minimum Fuse Size	170
Minimum Circuit Breaker Size	170
Maximum Fuse Size	350
Maximum Circuit Breaker Size	350
Minimum Wire Input	125% of circuit breaker size
Idle Amperage	32.4
Three Phase Electrical Specifications	
Voltage Output	208-245 based on input voltage
Output Amperage	200
Voltage Balance	2 - 5%
Minimum Wire to Generator	1 AWG to each idler (pre wired)
Minimum Wire to Load	3/0 AWG or based on load
Dimensions & Weights	
Enclosure (H X W X D)	30" X 28" X 42"
Installation Clarence (all sides)	12" to 18"
Approx. Total Shipping Weight	935 lbs.

The PL-60 Pro-Line Phase Converter is best sized for:	
Easy / Light Motor Loads - up to 60HP	
Examples of Easy Loads: Table Saw, Milling Machine ,Drill Press	
Medium Motor Loads - up to 50HP	
Examples of Medium Loads: Belt Sander, Grinder, Mixer	
Hard Motor Loads - up to 40HP	
Examples of Hard Loads: Gearhead Lathe, Dust Collector , Fan	
Very Hard Motor Load - up to 30HP	
Examples of Very Hard Motor Loads: Air Compressor, Sub. Pump	
CNC, Resistive and Inductive Loads - up to 100 Amps @240 volts	

Sizing Notes PL-80

For light/easy motor loads: Size rotary phase converter up one size above motor size

For medium motor loads: Size rotary phase converter 1.5 times larger then motor size

For heavy/hard motor loads: Size rotary phase converter double the size of motor load

For very hard motor loads: Size rotary phase converter 2.5 times larger then the motor load

For CNC, resistive and inductive loads: Size rotary phase converter double the size of load





Wired and Wireless Remote Switches



Twist-Lock Outlets and Plugs



Rubber Isolation Mounting Feet



